SAFE, DEPENDABLE, AND MODERN OFFSHORE SUPPORT

REGISTRATION

USCG Official Number 1215137 GRT / ITC 88 Net 60 IMO 9549023 Classification ID 09175598 Classification ABS Year Built 2009 Flag USA

Builder Master Boat Builders
Certifications Subchapters L & I, Oceans

Load Line Only ♣A1, ♣AMS,

MAIN CHARACTERISTICS

 Length overall
 150 ft
 (45.7 m)

 Beam
 36 ft
 (11 m)

 Depth
 12 ft
 (3.7 m)

 Max Draft
 13.5 ft
 (4.1 m)

 Min Draft
 7.5 ft
 (2.1 m)

PERFORMANCE

Notations

Max Speed 10 knots 100 gal/hr (379 l/hr)
Cruising Speed 8 knots 85 gal/hr (378.5 l/hr)

MACHINERY

2x Caterpillar 3508B Main Engines **Total Horsepower** 1,700 BHP Main Propulsion Convention Wheels **Total Horsepower** 1.700 BHP **Main Generators** 2 Caterpillar C-9 (2) 150 kW **Total Rating Bow Thrusters** 1 X Tunnel **Total Horsepower** 300 BHP **Power Generator** 480V/60Hz

CAPACITIES AND DISCHARGE RATES

500 Lt	Coi 576 DWT
1,080 lbs/ft ²	(5.25 t/m²)
70 ft x 27 ft	(1,890 ft²)
27.5 M X 9.2 M	(251 M²)
74,300 USG	(272.5 M³)
43,000 USG	(162.8 M³)
97,180 100%	, ,
1,290 Bbls	(205 M³)
10,000 USG	(37.8 M³)
1X 2,600 GPM	(1X 591 M³/hı
	1,080 lbs/ft ² 70 ft x 27 ft 27.5 M X 9.2 M 74,300 USG 43,000 USG 97,180 100% 1,290 Bbls 10,000 USG

ELECTRONICS

(1) Kongsberg Simrad SDP-01 DP-1 System Full Joy Stick Mode(2) DGPS Receivers

(2) DGPS Receivers

(1) MK4.2 2000m.Fan Beam

(2) Gyro compass (2) Wind sensors (2) Radars GMDSS (3) VHF Radios SSB Radios

ACCOMMODATIONS

Max Capacity 20 people (2) 4 Person Room (3) 2 Person Room (1) 6 Person Room

SPECIAL FEATURTES


A complete complement of Safety Standby Equipment, Scramble Net, Life Jackets, Blankets, Etc. FRC with Davit, Offshore Standby for 75 Persons


Discharge Rate 550 GPM (125 M³/hr)
Discharge Rate 550 GPM (125 M³/hr)

Discharge Rate 1,000 GPM (227 M³/hr)

NOTICE: The data contained herein is provided for convenience of reference to allow users to determine the suitability of the Company's equipment. The data may vary from the current condition of equipment which can only be determined by physical inspection. Company has exercised due diligence to insure that the data contained herein is reasonably accurate. However, Company does not warrant the accuracy or completeness of the data. In no event shall Company be liable for any damages whatsoever arising out of the use or inability to use the data contained herein.

www.labordemarine.com contact: (985)399-9066





www.labordemarine.com contact: (985)399-9066